

# Operating Instruction (TPM-10A)

## Features

- LCD display
- Insert design
- Simple appearance
- Two button batteries use for longer time
- Especially applied in refrigerator, chiller, deepfreeze etc.

## Technical parameter

- Measurement range:  $-50^{\circ}\text{C} \sim +70^{\circ}\text{C}$
- Using environment: Temperature:  $-10^{\circ}\text{C} \sim +50^{\circ}\text{C}$   
Humidity:  $5\% \sim 80\%$
- Accuracy:  $\pm 1^{\circ}\text{C}$
- Distinguish:  $1^{\circ}\text{C}$
- Power: two button battery ( LR44,1.5V)

## Instruction

- Open the battery cover and put in two LR44 batteries correctly, be assure not to turn over.
- Display when put in the batteries.Pls take out the batteries when not using for long time (Notes: First use pls take out the thin insulative slice)
- LCD display  $\text{H}^{\circ}\text{C}$  when temperature is higher than  $70^{\circ}\text{C}$ ;  
LCD display  $\text{L}^{\circ}\text{C}$  when temperature is lower than  $-50^{\circ}\text{C}$ .
- Insert size: 46 x 26.6mm